



Data sheet

Spare parts and accessories


Expansion valves TEA, TEAT, TEVA and TEAQ, size 20 and 85




TEA



TEAT



TEVA



TEAQ

Valve type	Size	See details on page #	Code no.
Inspection kits			
TEA, TEAT, TEVA, TEAQ	All	2	068G0064
Repair kits, orifice			
TEA, TEAT, TEVA, TEAQ	20 - 1	3	068G2050
	20 - 2	3	068G2051
	20 - 3	3	068G2052
	20 - 5	3	068G2053
	20 - 8	3	068G2054
	20 - 12	3	068G2055
	20 - 20	3	068G2056
	85 - 33	3	068G2057
	85 - 55	3	068G2058
	85 - 85	3	068G2059

Valve type	Size	Temperature setting	See details on page #	Code no.
Repair kits, element				
TEA	All	-50 °C / 0 °C	4	068G3250
	All	-20 °C / +30 °C	4	068G3252
TEAT	All	+35 °C / +65 °C	4	068G3262
	All	+55 °C / +95 °C	4	068G3260
	All	+90 °C / +130 °C	4	068G3261

No overhaul kit available.

For ordering new valves please see the Danfoss website.
TEAQ is out of production and cannot be ordered anymore.

Inspection kits:

Contains all gaskets, O-rings and sealings belonging to 1 valve size.
For detailed content, see specific pages mentioned above.














Repair kits, orifice:

Repair kit orifice contains all gaskets, O-rings, sealings and one orifice belonging to one valve size.
For detailed content, see specific pages mentioned above.


Repair kits, element:

Repair kit element contains all gaskets, O-rings, sealings and one element belonging to one valve size.
For detailed content, see specific pages mentioned above.

Inspection kit | Code number 068G0064 TEA, TEAT, TEVA and TEAQ, Size 20 and 85


 TEA	 TEAT		
 TEVA	 TEAQ		
1  = Alu.  Total no. = 2	2  = Alu.  Total no. = 1	3 (size 20)   Total no. = 1	3 (size 85)   Total no. = 1
4 (size 20)  = Fibre  Total no. = 3	4 (size 85)  = Fibre  Total no. = 3	5  = Alu.  Total no. = 1	

Repair kit, orifice | Code numbers: 068G2050 / 068G2051 / 068G2052 / 068G2053 / 068G2054 / 068G2055 / 068G2056 / 068G2057 / 068G2058 / 068G2059
TEA, TEAT, TEVA and TEAQ, Size 20 and 85



1 	2 	3 (size 20) 	3 (size 85) 	4 (size 20)
4 (size 85) 	5 	6 	7 	
Total no. = 2	Total no. = 1	Total no. = 1	Total no. = 1	Total no. = 3
Total no. = 3	Total no. = 1	Total no. = 1	Included in the repair kit 068G2050 only Total no. = 1	

Repair kit, element | Code numbers: 068G3250 / 068G3252 / 068G3260 / 068G3261 / 068G3262
TEA, TEAT, TEVA and TEAQ, Size 20 and 85



1 $\varnothing 36 \text{ mm}$ $\varnothing 1.42''$ Total no. = 2	2 $\varnothing 17.5 \text{ mm}$ $\varnothing 0.69''$ Total no. = 1	3 (size 20) $\varnothing 8 \text{ mm}$ $\varnothing 0.32''$ Total no. = 1	3 (size 85) $\varnothing 9 \text{ mm}$ $\varnothing 0.35''$ Total no. = 1	4 (size 20) $\varnothing 32 \text{ mm}$ $\varnothing 1.26''$ Total no. = 3	4 (size 85) $\varnothing 39 \text{ mm}$ $\varnothing 1.54''$ Total no. = 3
5 $\varnothing 26 \text{ mm}$ $\varnothing 1.02''$ Total no. = 1	6 1 of A or 1 of B or 1 of C	Bulb strap Total no. = 1			

